

Waldo Canyon Post Fire Restoration



Material Grading





Transition Zones





Channel Characterization



-Main Channel Flows

-Maintaining stream patterns in place





-End result is that each transition zone flows into the next leading structure.



-Rock Lining edges added stability to the fabric and kept water from jumping out of the channel.



-Successful seeding underneath fabric added stability right away to areas with heavy flows.

Adapted Checkdam Designs



We needed to Increase Stability



Increased rock armoring





-Fabric with
checkdams

Drop Structure Success

















Wood Strand Mulch



Volunteer Events!

- VOC
- Air Force Cadets
- Volunteer Firefighters



Thanks for choosing Habitat Management Inc!

